



## Paint and Corrosion Stripping – Case Study

### Fletcher Cresco, Wanganui Aeroworks

Wanganui Aeroworks, a company which specialised in all aspects of aerial applications such as fertiliser spreading and agriculture spraying, required removal of filiform corrosion and ceramic undercarriage coatings on an Ag-Aircraft.

The client required removal of corrosion and ceramic accumulated on the plane, a service that would need highly skilled Aquamax operators using the waterjetting process.

Facing a tight schedule, Aquamax operators worked for extensive hours over the weekend to complete the project in full, on time and in specification.

The waterjetting process done by the Aquamax team stripped the Ag-Aircraft clean from the coatings that required removal, including the painting, leaving it primed for a renewal job and delighting the client with the efficiency and quality of professional waterjetting.

#### Customer Outcomes

- ▼ Outsourced service
- ▼ No distortion to any surfaces
- ▼ All rivets cleaned of edgeline coatings and oxides
- ▼ Small amounts of water used easily contained and disposed of

I was impressed.  
Where do you get these guys from? How can we clone them for our operations?

**Rob Hartnell**  
Engineering Manager  
Wanganui Aeroworks



Corrosion and Ceramic Coatings



Coatings Stripped from Aircraft